

Fins:

Rocket Description		Recovery Information		Altimeter Two Data	
Owner:	Tanner, Chris Desti	Ejection Occurred		Apogee Altitude:	-
Rocket Name:	Nutech	• During Ascent	• At Apogee	Top Speed:	-
Type:	Sumo	• After Apogee	• During Descent	Burn Time (burn):	-
Length: (inches)	39"	• Ejection Failure		Peak Acc (Pacc):	-
Diameter: (inches)	4"	Parachute Deployment		Avg Acc (Aacc):	-
Fins:	4	• Full	• Partial	Coast Apogee (C2AP):	-
Listed Mass: (g)	907g	• Did not deploy		Apogee to Eject (AP2E):	-
Date of Construction:	4/1/2016	Parachute Descent		Ejection Alt. (EALt):	-
Recommended Motors: (G only)		• Stable Descent	• Tangled lines	Descent Speed (dESc):	-
RMS(G64-4, G71-4, G76-4)	SU(G38-4, G40-4, G77-4, G78-4, G79-4, G80-7	• Some swaying	• Sprial descent	Flight Duration (durA):	-
Center Gravity(CG):	26.25"	Reason for Recovery Failure		Altimeter Data Analysis	
Center Pressure(CP):	29.5	• Damaged Chute		Altimeter was jammed into the nose cone. The hole wasn't big enough so we jammed it in and then had to cut it out. We believe it didn't work because when we pushed it into the nose cone, the pressure changed and set it off. The data we received was inaccurate. As we	
Building Notes		• Tight Upper Body tube		Prediction vs Actual Analysis	
building was fine, all parts attached, package did not have any missing parts. The rocket went together smoothly, had a		• Improper setup			
Estimated Cd:		• Chute Separated			
Predicted Altitude:		• Motor Ejected			
Prediction Notes		• Unplanned Separation		We didn't get the right data so we can't compare anything. It looked roughly around 800 ft which is close to our prediction which was 840 ft. We launched into the wind causing the rocket to fly straight up. It was also calm the time we launched so I don't think anything really affected the altitude.	
We chose .34 for the Cd because it was in the middle of the other flight's Cds. Also, with that Cd it gave us a very good prediction altitude which is 840 ft. We chose 840 ft because again it was in the		• Other			
Launch Information		Descent Speed			
Date:		• Slow			
Time of Launch:		• Average speed		Lessons Learned	
Location:		• Very fast			
Rocket Mass(g):		Landing			
Motor:		• Soft			
Motor Mass(g):		• Tree		We learned that we should all agree on a design and not do anything another group member doesn't know about before doing it because if someone does the other members get upset. The building process is a long, thought out process that needs to take time. If you do it too fast then you might mess something up. You need to exactly what to do before you do it so you don't glue something on where it's not suppose to. The prediction process also needs to be thought out. There are a lot of variables that can affect your prediction so making sure all them are correct will help you. Making sure all the connections are correct when launching will allow your launch to go smoothly. We made sure of that and we were done in 10 or less minutes. As a class we learned is we need to take care of all the equipment and cameras when launching and recovering because some to those things can be broken.	
Altimeter Mass(g):		• Hard			
Liftoff Mass(g):		• Caught on Wire			
Wind Direction:		• Crash			
Wind Speed:		• Landed on Building		Recovery	
Igniter:		• Full Recovery			
No. of tries to ignite:		• Lost			
Ignition		• Not Recoverable			
• Successfull		• Parts lost		Distance & Direction from pad: East about 300 ft on the football practice fields	
• Caught on clips		• Motor Failure			
Trajectory		Recovery Notes			
• Straight-Up		landed on the fin and the nose cone bounced hard, chute didn't deploy all the way so it was coming down a little fast than average, the fin was lose when recovered			
• Corkscrew		Post Launch Information		Flight Grade	
• Into the wind		• Excellent			
• Spinning		• Good			
• Non-vertical		• Fair			
• Unstable		• Poor		Describe any damage to the rocket: The flight was excellent. The only bad thing was the altimeter. When recovered, the fin was lose because the fins hit first on the ground and bounced hard. Also, when looked at after the shock cord was stretched out and only holding on by a few strings. It about tore in half. Otherwise all the stickers and paint were still on and no damage to the body.	
Launch Notes		• Rocket cannot launch again			
set up was good, all connections were working, launched on 1st attempt, fast takeoff, very loud (thought it was louder than other sumos)		• Rocket cannot launch again			
Rocket Project Suggestions		• Rocket cannot launch again			